

5:20



FF/Wastegate Adaption

60

Fuel Open Loop

0

Meth Safety Mode (0-3)

0

Meth Trigger Mode (0-3)

0

Max Boost 1st

9.9

Max Boost 2nd

0.0

Max Boost 3rd

0.0

Future Use A

0

TMAP Setting

1

6-Cyl Timing Logging (0-6)

0

I8A0S = 4, IJE0S = 5

Options

Bit 0: Disable Fuel Control



Bit 1: Enable Manual Fuel Mapping



Bit 2: Disable Warmup Protection



Bit 3: Slow Speed CANbus



Bit 4: Disable IBA Safety Systems



CANCEL

SAVE